


Base assembly



PARTS LIST

You will need:

- 4x L630-3220 (Base 10ft)
- 4x L640-0080 (Corner joiner)
- 42x W05A (Brackets)
- 21x W05B (Brackets)
- 142x M01 (Nuts)
- 58x S03 (Hex head bolts)
- 84x S04 (T-head bolts)

USEFUL TIPS

Ensure the ground is level, this will make assembly much easier and faster.

Step 1.

Layout base components as per diagram below

