


Base assembly



PARTS LIST

You will need:

- 2x L630-3220 (Base 10ft)
- 2x L630-2596 (Base 12ft)
- 4x L640-0080 (Corner joiner)
- 38x W05A (Brackets)
- 19x W05B (Brackets)
- 130x M01 (Nuts)
- 54x S03 (Hex head bolts)
- 76x S04 (T-head bolts)

USEFUL TIPS

Ensure the ground is level, this will make assembly much easier and faster.

Step 1.

Layout base components as per diagram below

