


# Base assembly



## PARTS LIST

### You will need:

- 2x L630-3220 (Base 10ft)
- 2x L630-3844 (Base 12ft)
- 4x L640-0080 (Corner joiner)
- 46x W05A (Brackets)
- 23x W05B (Brackets)
- 154x M01 (Nuts)
- 62x S03 (Hex head bolts)
- 92x S04 (T-head bolts)

## USEFUL TIPS

Ensure the ground is level, this will make assembly much easier and faster.

## Step 1.

Layout base components as per diagram below

