


# Base assembly



## PARTS LIST

### You will need:

- 2x L630-3220 (Base 10ft)
- 2x L630-1972 (Base 6ft)
- 4x L640-0300 (Corner stakes)
- 16 x W05A (Brackets)
- 48 x M01 (Nuts)
- 48 x S03 (Bolts)

## USEFUL TIPS

Ensure the ground is level, this will make assembly much easier and faster.

Assemble the base upside down then turn over and move it into position once bolted together.

## Step 1.

Layout base components as per diagram below

