


Base assembly



PARTS LIST

You will need:

- 2x L630-2596 (Base 8ft)
- 2x L630-3220 (Base 10ft)
- 4x L640-0300 (Corner stakes)
- 17 x W05A (Brackets)
- 50 x M01 (Nuts)
- 50 x S03 (Bolts)

USEFUL TIPS

Ensure the ground is level, this will make assembly much easier and faster.

Assemble the base upside down then turn over and move it into position once bolted together.

Step 1.

Layout base components as per diagram below

